

NEWS RELEASE FOR IMMEDIATE RELEASE March 20, 2024

Hwy. 38 MM 2 – Buffalo - Railroad Crossing Injury Crash ***Corrected Release – Sequence of Events***

What: An SUV struck a BNSF vehicle at the railroad crossing

Where: BNSF railroad crossing on Hwy. 38 MM 2 @ Buffalo, ND

When: March 20th, 2024 @ approximately 9:35 am

Road Conditions: Dry

Type of Crash: Two vehicle T-Bone crash

Agencies Involved: NDHP, Cass County SO, Buffalo FD & 1st Responders, Page Ambulance,

Casselton Ambulance, Sanford Ambulance

Vehicle No. 1: 2017 GMC Acadia

Driver No. 1: Patty Hoag, 72 YOA female, Hunter, ND – minor injuries

Restraints: Restrained & air bag deployment

Charges: None

Passenger No. 1: Myron Hoaq, 75 YOA male, Hunter, ND – minor injuries, restrained & air

bag deployment

Passenger No. 2: Laurel McPherson, 71 YOA female, Erie, ND – minor injuries, restrained

Vehicle No. 2: 2016 Ford F250 BNSF High Rail truck

Operator: Travis Fortier, 47 YOA male, Jamestown, ND – minor injuries

Restraints: Under investigation – no air bag deployment

Charges: Not applicable

NARRATIVE:

On March 20th, 2024, at approximately 9:35 am, a two-vehicle injury crash occurred at the railroad crossing on Hwy. 38 MM 2 at Buffalo, ND. The railroad crossing is a BNSF crossing with stop arms and lights.



A BNSF Ford F250 High Rail pickup was westbound traveling on the BNSF main line track. The Ford entered the crossing on the railroad tracks and into the path of the southbound GMC. The Ford struck the drivers side of the GMC in a T-bone type crash.

The stop arms and lights to notify traffic approaching the crossing on Hwy. 38 were not down or activated at the time of the crash. Typically, BNSF high rail vehicles such as this pickup do not trigger the automatic deployment of these traffic safety devices.

The operator of the Ford was transported to Sanford Hospital in Fargo with minor injuries. All three occupants of the GMC were also transported to Sanford Hospital in Fargo for minor injuries. Page, Casselton, and Sanford Ambulance Services worked together on the care and transport of all patients.

The crash remains under investigation by the NDHP.

For More Information Contact:

Captain Bryan Niewind (701) 320-1309 bniewind@nd.gov